

UNAPPROVED PART NOTIFICATION

NO. 97-000
March 21, 1997

AFFECTED ENGINES: Pratt & Whitney JT9D and Rolls-Royce
RB211-22B and -535 engines

PURPOSE:

The purpose of this notification is to advise all owners, operators, maintenance entities, and manufacturers of the above listed engine models of certain scrap parts that have been stolen from a repair facility.

BACKGROUND:

The following parts were determined to be scrap and were awaiting mutilation at the time of the theft. The possibility exists that an attempt may be made to sell these parts on the open market.

JT9D Engine:

Part Number	Serial Number	Description
808825	RZ2696	Seal Assembly
808823	GU9780	Seal Assembly
708480	HP0565	ST2 Seal Ring
708480	ZV6561	ST2 Seal Ring
797576	RH0515	ST1 Air Seal
745870	115/1	ST5 Ring
736673	3-90	ST3 Shroud
777987	11-19	ST7 Shroud
799785	T27169	ST5 Disc
645833	IX7933	Hub Rear

RB211-22B Engine:

LK57024	PACF1541	Fail-Safe Shaft
---------	----------	-----------------

RB211-535 Engine:

LK82701	BAEF4041	I.P. Shaft
LK80622	LQDY5656	HP Turbine Disc
LK76902	EEBH3497	I.P.T. Disc
LK76902	EEBH3011	I.P.T. Disc
LK82454	SEBH4484	L.P.T. Disc ST2
UL19436	BAEF3642	I.P.T. Shaft
UL19432	BAEF3612	L.P.T. Shaft

RECOMMENDATIONS:

Regulations require that type certificated products conform to their type design. Owners, operators, maintenance

entities, and manufacturers should prevent these engine parts from being installed on type certificated products.

FURTHER INFORMATION:

Further information may be obtained from the Federal Aviation Administration (FAA) Flight Standards International Field Office referenced below. The FAA would appreciate any information concerning the discovery of these parts from any source, the means used to identify the source, and the actions taken to remove them from aircraft and/or stock.

This notice originated from the FAA Flight Standards International Field Office in Gatwick, England, phone 011-44-1293-573933, fax 011-44-1293-573992 and was published through the Suspected Unapproved Parts Program Office, AVR-20, phone (703) 661-0580, fax (703) 661-0113.